

Tel: +852 2910 6174 AFS: VHHHYNXX Fax: +852 2910 1180 E-mail: aic@cad.gov.hk	AERONAUTICAL INFORMATION SERVICES	NOTAM Summary Series: A
	HONG KONG CIVIL AVIATION DEPARTMENT	
	VHHH	11 AUG 2022
THE FOLLOWING NOTAM SERIES A WERE STILL VALID AT 00:00 ON 11 AUG 2022 NOTAM NOT INCLUDED HAVE EITHER BEEN CANCELLED, TIME EXPIRED, SUPERSEDED BY AIP SUPPLEMENT OR INCORPORATED IN THE AIP HONG KONG CIVIL AVIATION DEPARTMENT		

FIR

VHHK - HONG KONG FIR

A0682/22 NOTAMN

- Q)** VHHK/QWMLW/IV/BO/W/000/080/2226N11357E002
A) VHHK **B)** 2208110000 **C)** 2208111000
E) FIRING EXER IN THE NORTHERN PORTION OF DANGER AREA VHD5 AND ADDN
SURROUNDING AREA BOUNDED BY 222650N 1135626E 222650N 1135810E
222428N 1135810E AND 222428N 1135626E.
SAFETY ALT FL140.
ALL ACFT MUST REMAIN CLEAR OF THE AREA.
F) SFC **G)** 2400M AMSL

A0555/22 NOTAMN

- Q)** VHHK/QAFTT/IV/BO/E/000/999/2003N11500E256
A) VHHK **B)** 2208110000 **C)** 2208250000
E) TRIGGER NOTAM-AIP AMENDMENT 8/22 (AIRAC) WEF 11 AUG 2022:
-REALIGNMENT OF OIL RIG SUPPORT HELICOPTER TRACK VW AND HONG
KONG-MACAO HELICOPTER ROUTE C1 TO BYPASS AN OFFSHORE WINDFARM

A0466/22 NOTAMN

- Q)** VHHK/QRDXX/IV/BO/W/000/999/2003N11500E256
A) VHHK **B)** 2206160915 **C)** PERM
E) ZG(D)155 RENAMED AS ZJ(D)208
- TIME OF ACTIVITY: DAILY 0030-1200
- NATURE OF HAZARD: GROUND TO AIR FIRING

A0462/22 NOTAMN

- Q)** VHHK/QXXXX/IV/NBO/E/000/999/2003N11500E214
A) VHHK **B)** 2206151800 **C)** PERM
E) REF AIP HK ENR 1.8 PARA 8.2B, FLAS LEVELS FOR A470 AND M503
ARE REMOVED.

TWO NEW PARA ARE ADDED IN ENR 1.8 PARA 8.2:

AIP HK ENR 1.8 PARA 8.2G 'FLAS BTN HONG KONG FIR AND XIAMEN CONTROL
AREA':

FLAS LEVELS FOR ROUTE A470:

- EXIT XIAMEN CONTROL AREA TO HONG KONG FIR: S0660, S0720, S0780
- EXIT HONG KONG FIR LDG
ZSAM, ZSQZ, ZGMX: S0510, S0630, S0750 (SUBJ COOR)
ZSFZ, ZSWY, ZSWZ: S0630, S0750

AIP HK ENR 1.8 PARA 8.2H 'FLAS BTN HONG KONG FIR AND SHANGHAI
CONTROL AREA':

FLAS LEVELS FOR ROUTE A470:

- EXIT SHANGHAI CONTROL AREA LDG VHHH OR VMMC: FL280, FL300
- EXIT SHANGHAI CONTROL AREA AND TRANSITING HONG KONG FIR: FL280,
FL300, FL360, F380
- EXIT HONG KONG FIR LDG:
ZSHC, ZSYW, ZSNB: S0810 (SUBJ COOR), FL330
OTHER AD: S0810 (SUBJ COOR), FL330, FL350, FL390

FLAS LEVELS FOR ROUTE M503:

- DEP FM VHHH OR VMMC AND LDG:

ZSPD: FL330
ZSQD, ZSYT, ZYTL: FL330, FL350
- DEP FM ZSPD, ZSQD, ZSYT, ZYTL LDG VHHH: FL300

A0255/22 NOTAMN
Q) VHHK/QXXXX/IV/NBO/E/000/999/2003N11500E025
A) VHHK **B)** 2204201800 **C)** PERM
E) REF AIP HK ENR 1.8 PARA 8E, FLAS BETWEEN HONG KONG FIR AND ZHANJIANG CONTROL AREA IS AMENDED AS FLAS BETWEEN HONG KONG FIR AND NANNING CONTROL AREA. FLAS LEVELS S0660 AND S0720 ARE ADDED FOR AIRCRAFT LANDING BOAO AIRPORT VIA ROUTE A202.

AERODROMES

VHHH - HONG KONG/ INTERNATIONAL

A0688/22 NOTAMN
Q) VHHK/QNMAU/IV/NBO/AE/000/999/2219N11355E005
A) VHHH **B)** 2208150200 **C)** 2208150400
E) LUNG KWU CHAU DVOR/DME 'LKC' 113.20 MHZ/CH79X NOT AVBL DUE MAINT.

A0686/22 NOTAMN
Q) VHHK/QMXLC/IV/M/A/000/999/2219N11355E005
A) VHHH **B)** 2208110001 **C)** 2208120730
D) DLY 0001-0730
E) TWY C BTN TWY C6 AND TWY C9 CLSD DUE WIP

A0681/22 NOTAMN
Q) VHHK/QNMAU/IV/NBO/AE/000/999/2219N11355E005
A) VHHH **B)** 2208170200 **C)** 2208170400
E) SIU MO TO DVOR/DME 'SMT' 114.80 MHZ/CH95X NOT AVBL DUE MAINT.

A0680/22 NOTAMN
Q) VHHK/QNDAU/IV/BO/AE/000/999/2219N11355E015
A) VHHH **B)** 2208240130 **C)** 2208240330
E) CHEUNG CHAU DME 'CH' 1094 MHZ NOT AVBL DUE MAINT.

A0673/22 NOTAMN
Q) VHHK/QMXLC/IV/M/A/000/999/2219N11355E005
A) VHHH **B)** 2208121716 **C)** 2208122300
E) THE FLW TWY AND TXL CLSD DUE WIP:
TWY B BTN TXL R AND TXL U
TWY T BTN TWY B AND TWY H
TXL P1 BTN TWY N AND TXL P

A0672/22 NOTAMN
Q) VHHK/QMXLC/IV/M/A/000/999/2219N11355E005
A) VHHH **B)** 2208130001 **C)** 2208130730
E) TWY C BTN TWY C5 AND TWY C8 CLSD DUE WIP

A0667/22 NOTAMN
Q) VHHK/QMXLC/IV/M/A/000/999/2219N11355E005
A) VHHH **B)** 2208080801 **C)** 2208131330
D) AUG 08 09 12 13 0801-1330
E) THE FLW TWY CLSD DUE WIP
TWY H WEST OF TWY H2
TWY J WEST OF TWY H2
TWY J1
TWY J2
TWY K1
TWY K WEST OF TWY Q1

A0637/22 NOTAMN
Q) VHHK/QOBXX/IV/NBO/A/000/999/2219N11355E005
A) VHHH **B)** 2208010707 **C)** 2208312359
E) MULTIPLE MARINE AND LAND OBST PROJECTED ALONG

RWY 07L EXTD CL PSN:

- 1) 540M FM DER AT 28 FT AMSL
- 2) 817M FM DER AT 56 FT AMSL
- 3) 1170M FM DER AT 72 FT AMSL
- 4) 1180M FM DER AT 75 FT AMSL

RWY 25R EXTD CL PSN:

- 1) 373M FM DER AT 28 FT AMSL
- 2) 735M FM DER AT 56 FT AMSL
- 3) 1882M FM DER AT 113 FT AMSL
- 4) 2435M FM DER AT 154 FT AMSL
- 5) 3595M FM DER AT 168 FT AMSL

A0623/22 NOTAMR A0608/22
Q) VHHK/QMRXX/IV/NBO/A/000/999/2219N11355E005
A) VHHH **B)** 2207280619 **C)** 2208262359EST
E) REF AIP SUP 06/22 PARA 1.1, THE NORTH RUNWAY (RWY 07L/25R) IS AVAILABLE FOR OPERATION FAMILIARISATION. PILOTS ARE REMINDED TO STAY VIGILANT FOR POTENTIAL EXTERNAL RFI ON LANDING.

A0549/22 NOTAMR A0244/22
Q) VHHK/QXXXX/IV/NBO/A/000/999/2219N11355E005
A) VHHH **B)** 2207120152 **C)** 2210111559EST
E) WHEN SOMEONE ON BOARD A FLIGHT INBOUND TO HONG KONG INTERNATIONAL AIRPORT IS DETECTED WITH SYMPTOMS COMPATIBLE WITH CORONAVIRUS DISEASE 2019 (COVID-19), THE PILOT-IN-COMMAND SHALL NOTIFY HONG KONG ATC ON FIRST CONTACT OR IF ALREADY IN CONTACT WITH HONG KONG ATC AS SOON AS SYMPTOMS ARE OBSERVED SO THAT ATC CAN ALERT THE PORT HEALTH AUTHORITY.

A0537/22 NOTAMR A0377/22
Q) VHHK/QXXXX/IV/NBO/AE/000/999/2219N11355E005
A) VHHH **B)** 2207080152 **C)** 2209302359
E) DUE VOR 'NLG' NOT AVBL FOR VHHH, THE FLW RWY 25L NON-RNP 1 SID FOR CONTINGENCY USE ARE AFFECTED: BEKOL 2B, LAKES 2B, OCEAN 2B AND PECAN 1B.
ACFT WITH EXEMPTION FM RNP 1 REQUIREMENT SHALL FOLLOW NLG U/S ALTERNATIVE PROC IN AIP VHHH AD 2.22 PARAGRAPH 2.2.3.5.

A0531/22 NOTAMN
Q) VHHK/QPIXX/I/NBO/A/000/999/2219N11355E005
A) VHHH **B)** 2207080000 **C)** 2209302359EST
E) REF AIP SUP 06/22 ATTACHMENTS AD-2-VHHH-IAC-06A AND AD-2-VHHH-IAC-06B
ILS APCH RWY 25R CONSISTS OF RNAV TRANSITION AND ILS FINAL APCH SEGMENT. ILS APCH MODE SHALL NOT BE ACTIVATED UNTIL PASSING WAYPOINT TOPUN. PILOTS SHALL COMPLY WITH PUBLISHED ALTITUDE RESTRICTIONS WHEN DESCENDING VIA RNAV TRANSITION FOR TERRAIN AND OBSTACLE CLEARANCE. AFTER TOPUN, CROSS VH536 AT 1800 FT UNLESS ESTABLISHED ON GLIDESLOPE. FOR DETAILS OF OPERATING REQUIREMENTS REFER TO AIC 11/22.

A0521/22 NOTAMN
Q) VHHK/QMXLC/IV/NBO/A/000/999/2219N11355E005
A) VHHH **B)** 2207080000 **C)** 2412312359EST
E) REF PAGE 1 OF ATTACHMENT TO AIP SUP 06/22, THE FLW TWY ARE NOT AVBL FOR OPS DUE WIP:
TWY A WEST OF TXL R,
TWY A1, TWY A2, TWY A3, TWY A4, TWY A5,
TWY A6 NORTH OF TWY A,
TWY A7,
TWY A8 NORTH OF TWY A,
TWY A9,
TWY A10 NORTH OF TWY A,
TWY A11 NORTH OF TWY A,
TWY A12,
TWY B WEST OF TXL P

A0520/22 NOTAMN
Q) VHHK/QMXXX/IV/NBO/A/000/999/2219N11355E005
A) VHHH **B)** 2207080000 **C)** PERM
E) REF PAGE 1 OF ATTACHMENT TO AIP SUP 06/22, THE FLW TWY ARE AVBL FOR

OPS:
TWY C, TWY C1, TWY C2, TWY C3, TWY C4, TWY C5, TWY C6, TWY C7,
TWY C8, TWY C9, TWY C10, TWY C11, TWY C12,
TWY D, TWY D1 BTN TWY C AND TWY D, TWY D1 BTN TWY E AND TWY F,
TWY D4, TWY D5,
TWY E, TWY E3,
TWY F,
TWY Y,
TWY Z, TWY Z1, TWY Z2, TWY Z3,
TWY B6,
TWY T BTN TWY A AND TWY F.
CONSEQUENTLY, AIP SUP 14/21 IS CNL.

A0518/22 NOTAMN
Q) VHHK/QMRXX/IV/NBO/A/000/999/2219N11355E005
A) VHHH **B)** 2207080000 **C)** 2209302359EST
E) REF AIP SUP 06/22 PARA 1.1, THE NORTH RWY (RWY 07L/25R) IS AVBL FOR
OPS FAMILIARIZATION. CONCURRENTLY THE CENTRE RWY (RWY 07C/25C) IS
CLSD FOR RECONFIGURATION AND THE ASSOCIATED AERODROME DATA IN AIP
HONG KONG SHALL NOT BE USED.

A0506/22 NOTAMR A0209/22
Q) VHHK/QXXXX/IV/NBO/A/000/999/2219N11355E005
A) VHHH **B)** 2206290547 **C)** 2209281559EST
E) IN VIEW OF THE LATEST SITUATION OF COVID-19, THE HONG KONG SPECIAL
ADMINISTRATIVE REGION GOVERNMENT IS IMPLEMENTING VARIOUS MEASURES
FOR PERSONS ARRIVING AT HONG KONG.

DETAILS INCLUDING PERSONS APPLICABLE, BOARDING, COMPULSORY
QUARANTINE AND TESTING REQUIREMENTS CAN BE FOUND IN
[HTTPS://WWW.CORONAVIRUS.GOV.HK/ENG/INBOUND-TRAVEL.HTML](https://www.coronavirus.gov.hk/eng/inbound-travel.html)

AIR CREWS ARE SUBJECT TO SPECIFIC ARRANGEMENTS WHICH CAN BE FOUND
IN [HTTPS://WWW.CORONAVIRUS.GOV.HK/ENG/EXEMPTED-PERSONS-FAQ.HTML](https://www.coronavirus.gov.hk/eng/exempted-persons-faq.html)

FOR ENQUIRIES, PLEASE CONTACT THE DESIGNATED HEALTH AUTHORITY AS
LISTED IN AIP HONG KONG GEN 1.1.

A0492/22 NOTAMN
Q) VHHK/QFAXX/IV/NBO/AE/000/999/2219N11355E005
A) VHHH **B)** 2206240334 **C)** PERM
E) REF AIP AD 1.5, DATE OF CERTIFICATION OF VHHH IS REVISED TO 1
JUNE 2022 AND IS VALID FOR 1 YEAR.

A0118/22 NOTAMN
Q) VHHK/QNVAU/IV/BO/AE/000/999/2219N11355E005
A) VHHH **B)** 2202230940 **C)** PERM
E) NANLANG VOR 117.7 MHZ 'NLG' NOT AVBL FOR OPERATIONAL USE FOR
VHHH INSTRUMENT FLIGHT PROCEDURES.

VHSS – SHEUNG WAN / SKY SHUTTLE HELIPORT

A0660/22 NOTAMR A0629/22
Q) VHHK/QFPLC/IV/B/A/000/999/2217N11409E005
A) VHSS **B)** 2208050223 **C)** 2208142359EST
E) REF AIP AD 3, TEMPO CLOSURE OF HLP DUE BORDER CONTROL.

AIP SUPPLEMENTS STILL IN FORCE AT 0000 UTC ON 11 AUG 22:

2021: 07 15

2022: 05 06 07 10 11 12

LATEST PUBLICATIONS AT 0000 UTC ON 11 AUG 22:

AIP SUP 12/22

AIC 23/22

AIP AMDT 10/22

AIRAC AIP PUBLICATION EFF 8 SEP 22 – NIL